



**HEXAGON**

---

**Release Notes**  
**ESPRIT EDGE 2024.3**

31 July 2024

# Contents

|  |           |
|--|-----------|
| <b>Welcome to ESPRIT EDGE!</b> .....                                     | <b>3</b>  |
| <b>Move Machine Axes</b> .....   | <b>3</b>  |
| <b>Probing C-axis Center Find</b> .....                                  | <b>4</b>  |
| Post processor language additions for rotary probing:.....               | 5         |
| <b>5-Axis Circle Segment Finishing – Passes from drive profile</b> ..... | <b>6</b>  |
| <b>5-Axis Remachining (Preview)</b> .....                                | <b>7</b>  |
| <b>Nexus Application 3D Whiteboard</b> .....                             | <b>8</b>  |
| <b>End of life of Gear and Cam commands</b> .....                        | <b>9</b>  |
| <b>Issues fixed in ESPRIT EDGE 2024.3</b> .....                          | <b>10</b> |


# Welcome to ESPRIT EDGE!

Welcome to the evolution of production CAM software. Welcome to ESPRIT EDGE!

ESPRIT EDGE 2024.3 introduces a host of new features and enhancements. We are committed to continually developing, improving, enhancing, and innovating.

Discover below what's new with the ESPRIT EDGE 2024.3 version.

## Move Machine Axes



Is the machine's machining envelop large enough for machining the workpiece? Is the workpiece raised enough to reach all the features of the part? Is the tool long enough to reach the floor?


A new capability in ESPRIT EDGE helps answering such questions: In machine view, a new control enables moving the programmable axis of the machine and get a real time feedback on possible collisions.

What you need to know:

- Go to **Home** >> **Show/Hide** and select **Machine Axes** to turn on the visibility of axis control.

- Select a tool assembly in the tool manager to load or select a tool while moving axes.
- Toolbar at the top of the Machine Axes pane enables:
  - Rest all axes to their Home positions.
  - Position axes relatively to the workpiece by digitizing a face of the workpiece.
  - Set the collision handling either by ignoring or reporting or stopping motion on collision.

## Probing C-axis Center Find



A new cycle type for the Probing cycle enables probing of a rotary axis using only rotary motions to find the centre of a feature on the part.

The cycle accepts probing of a hole, a circular boss, a pocket or a rib on the part.

In all scenarios, the centre of the feature (median plane, hole/boss centre) must intersect the C-axis of rotation.

After positioning the part at the centre of the feature, the system performs rotary motions on both sides of the part till contact.

The result of the probing cycle can be used to update the workoffset.



## Post processor language additions for rotary probing:

*New example:*

- **Ex\_Probe\_CAxisCenterFind**

Ex\_Probe\_CAxisCenterFind generates the code for a probing cycle that finds the center of an internal or external feature by rotating the rotary axis clockwise and counterclockwise.

*New formattable dimension:*

- **ProbeCenterlineDistance**

Specifies the distance from the C-axis center of rotation to the measurement position in a C axis Center Find cycle. To be used only with G68 tilted work plane function.

*New Symbolic Codes:*


- **ProbeZCAxisCenterFind**

ProbeZCAxisCenterFind designates the code for a probing cycle that finds the center of an internal or external feature when probe along the Z axis.

- **ProbeXCAxisCenterFind**

ProbeXCAxisCenterFind designates the code for a probing cycle that finds the center of an internal or external feature when probe along the X axis.

## 5-Axis Circle Segment Finishing – Passes from drive profile



The 5-Axis Circle Segment Finishing cycle adds an option to generate cut passes by offsetting a drive profile.

It enables creation of continuous passes at either the top or the bottom of the zone to be machined, preventing leaving any residual material in a critical area.


This option is an alternative to the existing option creating cut passes perpendicular to a user-defined direction.

In both cases, the cycle automatically positions the tool axis to optimize cut pass coverage on the planar and curved face(s) and to avoid collisions between the tool assembly and the model.

Drive profile can be defined by selection of loops or of edges of the model, either at the bottom (option Lower Profile Offset) or at the top (option Upper Profile Offset) of the area to machine.

The selected Edges or Loops must be at the border of the Part and Check elements.

## 5-Axis Remachining (Preview)




The 5-axis Remachining cycle is still in Preview. To see the new cycle, go to File > Options > Preview Features and check Enable 5x Remachining.

With ESPRIT EDGE 2024.3, there is more control over the shape of the passes: 2 new options create a central passes cleaning the centre of the corner uniformly without residual material.

Concentric


Concentric and Central Pass

Central Pass Offset



There is also a new tangent pass extension that extend passes outside opened extremities.

# Nexus Application 3D Whiteboard



ESPRIT EDGE 2024.3 introduces the connection to Nexus Applications and Extensions. 3D Whiteboard is the first Nexus application available.

With this free version of 3D Whiteboard, you can try it out and create up to 3 projects. 3D Whiteboard allows you to:

- **Easy collaborate**  
Share design changes and queries directly with customers or your extended team, with no CAD software required.
- **Increase productivity**  
Use intuitive tools to collaborate with multiple stakeholders in a browser to review and agree to any changes.
- **Reduced costs**  
Remove the need for complicated email threads and avoid mistakes.





- Comment and mark up  
Synchronize design changes instantly, capture key moments of a meeting and return to specific view whenever needed.

To use Nexus 3D Whiteboard, you would need to create a Nexus account if you don't have one already. Log into your Nexus account through ESPRIT EDGE by clicking on the "Connect to Nexus" button on the top right of ESPRIT EDGE (next to the Help) and then you can share your design(s) by using the "Share in 3D Whiteboard".

## **End of life of Gear and Cam commands**

Gear and Cam generator commands are being discontinued because of technology obsolescence. There are several profile generators available online that can replace these commands.

# Issues fixed in ESPRIT EDGE 2024.3

Version 2024.3.2430.1782

| Description  | Issue Number (s) |
|--|------------------|
| API – Typo in enumerated espHoleCycleType  | SW 290761        |
| API – Objects Tool1 ToolTip does not return the tool tip value   | SW 270223        |
| API – Depth from Chamfer Diameter returned the wrong value   |                  |
| Analysis – Curvature analysis graphic problem  |                  |
| Annotation – Auto Dimension only works correctly on XYZ plane  | SW 297353        |
| CAD exchange – Issues with stp file used as stock  | Forum 139704     |
| Features Manager – Features and operations cannot be edited through contextual menu after copy/paste   | SW 307546        |
| Features Manager – Renaming feature group creates duplicate toolpaths when applying process            | SW 307234        |
| Features Manager – Renaming feature group deletes any feature groups after a feature/operation removal | SW 307324        |
| Features Manager – Renaming feature group prevents feature/operation to be renamed                     | SW 307234        |
| Features Manager – Missing ability to drag and drop features in and out of feature sets                | SW 302897        |
| Geometry – First point array is not considered when Create Hole Feature is set to YES                  | 02053762         |
| Knowledgebase – Using Feeds and Speeds from KBM multiplies feedrate listed by number of flutes         | SW 301904        |
| Links – Cannot post because of links failure   | 02263620         |
| Links – Link error in file created in TNG  | 02263717         |
| Links – Background simulation issue because no rotary solution is found                                | 02249515         |
| Links – Feedrate links issue for deburring cycle   | 02249297         |
| Links – Link calculation failing between two operations  | SW 306389        |
| Links – Park to Home Creates Unnecessary Link Movement   | SW 300309        |
| Links – Wrong head rotation caused a machine collision   |                  |
| Links – Collinear axis tool change links   |                  |
| Links – Barfeeder drops part on rebuild  |                  |
| Milling – Process cannot be applied when using custom mill   | SW 305966        |
| Milling – ProfitMilling hybrid strategy engagement issue   | 02241133         |
| Milling – Pocket operation is not cutting to depth   |                  |

| Description   | Issue Number (s)                 |
|---|----------------------------------|
| Milling – Pocket feature with arc gouges the part   |                                  |
| Milling – Update Rotary Machining Cutter Comp Error to Warning                            |                                  |
| Milling – System crashing with trochoidal machining                                       | 02271944                         |
| Milling – Tool missing length compensation register                                       | 02244739                         |
| Post Processor – Park outputs XY position when position is not used                       | SW 305990                        |
| Post Processor – Unable to post when a station is not selected in park operation          | SW 304788                        |
| Post Processor – Cannot post due to very large file                                       | 02236484                         |
| Post Processor – Problem output for posts that support peck but not use Peck Formattable  |                                  |
| Post Processor – Circle Mode is ignored for helical NC output                             | 02264411                         |
| Simulation – FreeTurn insert gouges the part in simulation                                | 02248816                         |
| Simulation – Part in setups 2 and 3 are unclamps in simulation                            | SW 305303                        |
| Simulation – Collision is not detected early enough                                       | 02015631<br>02168541<br>02168630 |
| System – Crash when inserting tapping operation into a feature group                      | 02257264                         |
| System – Crash when switching to production mode with 2 workpieces mounted on sub spindle | SW 302681                        |
| System – Crash on rebuild of pocket operation   | SW 274577                        |
| System – Processing of FreeForm Geometry setting is not saved with document               | SW 306034                        |
| System – Crash when creating operations causes by incorrect position of sync              | SW 305389                        |
| System – Performance issue with big parts   | 02233701                         |
| System – Crash after deleting a setup   | 02238307                         |
| System – After a setup 2 is added, operations are duplicated after the first one          | SW 303721                        |
| System – Crash when operation is added after suppressed operations                        | 02235347                         |
| System – Crash creating Report Generator  | SW 303630                        |
| System – NC File Folder does not retain any Collapse Path setting                         | SW 300730                        |
| System – Allow ability to switch between IPR and IPM in Custom Drilling operations        | SW 294446                        |
| System – System crashed when opening a ZIP file with axis with invalid limits             |                                  |
| System – Park gets WOT if default work offset transformation is set                       |                                  |
| System – Incorrect work offset chosen on operation creation                               | SW 309292                        |

| Description  | Issue Number (s) |
|--|------------------|
| System – Select all takes a very long time with 168 parts                        |                  |
| System – Posting NC Code Really Slow with 168 parts                              |                  |
| System – Issue with setting WOT shift  | 02263581         |
| Tooling – Legacy Holder Creator set as an extension                              | SW 303492        |
| Tooling – Slot Mills with thickness ≤ 0.02” cannot be created                    | SW 297261        |
| Tooling – Cannot save file, Adaptive Item file reference is removed              |                  |
| Toolpath – 5-axis Port Finishing and Collision Detection Trim has collisions     | SW 303108        |
| Toolpath – Inconsistent tool axis at end extremities of lateral passes           | SW 302987        |
| Toolpath – Swarf bug with Last offset = 0  | SW 302987        |
| Toolpath – Bad transition move with ProfitMilling                                | SW 263843        |
| Turning – Manual turning cycle to engage tailstock results in no workplane error | SW 302953        |
| Turning – Incorrect rotary solution solver for ID turning operation              | SW 269140        |
| Turning – Simulation makes extra move with 3x turning                            |                  |
| Turning – FreeTurn Tool not aligned with holder                                  |                  |
| Turning – Missing Tool Change in Production Mode                                 | SW 307820        |
| Turning – Rebuild groove operation crash the system                              | 02275888         |
| Wire EDM – Long file load time   | SW 303223        |
| Wire EDM – Pivot progressive segment is wrong and not the same back and forward  | 02263408         |
| Wire EDM – AGIEVISION, number of cuts lost causing REBUILD to fail               | 02321424         |
| Wire EDM – Dual rotary scenario, incorrect PRIMARY axis value override           | 02376588         |
| Wire EDM – Rebuild of operation AGIEVISION Offset information are lost           | 02329372         |
| Wire EDM – Rotary values are no longer displayed in the program list             | 02257220         |